DESIG	PH	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECK	(ED	APPROVED	DRAWING NO. REV. A
	#	#	DSI 9323 SHEET 1 OF 1
DATE			TITLE SCALE
06.03.21			OVERSIZED INSERT REPLACEMENT NTS
Α		06.03.21	NEW ISSUE

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D206-628 REV. E OR REV. D

REF. CANADIAN STC: SH98-14 ISSUE 2 REF. FAA STC: SA00500SE

PURPOSE To allow replacement of inserts (rivnuts) in the D2841-041/-042 and

D2842-041/-042 steps with larger inserts for situations where the insert holes are

oversized because of damage.

PROCEDURE

It is acceptable to replace inserts in D2841-041/-042 or D2842-041/-042 steps as follows:

- Open existing insert holes to Ø0.413" ('Z' drill). Deburr and touch up holes with MIL-P-85582 or MIL-P-23377 primer. Install NAS1329C5KB125 or NAS1329H5KB125 or NAS1329H5KB125 inserts.
- 2) Open corresponding holes in D2844-1, D2844-3, or D2845 arms to Ø0.323 ('P' drill).
- 3) Install step on aircraft per IIN-D206-628, however for all modified holes substitute the AN3C4A bolt and AN960C10 washer with AN5C5A or AN5-5A bolt and AN960C516 or AN960JD516 washer.

(ref: Figure 4 of IIN-D206-628 Rev.E, page 9)

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

APPROVED

D. SHEPHERD (DE # 02)

DATE: 06.03.21
CERT. NO.: SH98-14
ISSUE NO.: 2